


COM		
ATIS	136.525	GATWICK INFO
TWR	124.230, 121.500*	GATWICK TOWER *Emergency On Request
	134.230 (As directed by ATC)	
	121.955	GATWICK DELIVERY
	121.805 (GMC)	GATWICK GROUND
	121.605	GATWICK FIRE

VAR 0.5°E - 2022  
N  
Annual Rate  
of Change 0.19°E

**WARNING**  
Runways have displaced thresholds.  
The take-off runway starts before the threshold  
markings in the pre-threshold area which is  
indicated by white centreline arrows.  
Aircraft entering the runway in the pre-threshold  
area should begin their take-off roll here and not  
wait until the threshold to apply take-off thrust.

RUNWAY/TAXIWAY/APRON PHYSICAL CHARACTERISTICS		
APRON / RWY / TWY	SURFACE	BEARING STRENGTH
RWY 08R/26L	Grooved Asphalt	100/F/C/W/T
RWY 08L/26R	Grooved Asphalt	100/F/C/W/T
TWYs V & W	Concrete	59/R/D/W/T
TWYs T & Y	Concrete/Asphalt	55/R/C/W/T
TWY ER	Asphalt	50/F/C/W/T
TWYs Other (Concrete)	Concrete	89/R/C/W/T
TWYs Other (Asphalt)	Asphalt	100/F/C/W/T
Apron - Parking Stands	Concrete	89/R/C/W/T
Apron - Parking Stands	Concrete Block Paving	100/F/C/W/T



CHANGE (4/26): STAND 178L, 178R & 180R MODIFIED. WARNING BOX.