


A380/AN225 Ground Movement
 Operational Taxiways
 Aprons

VAR 0.0°W - 2022
 N
 Annual Rate
 of Change 0.20°E



Hot Spots
HS1
 If instructed to taxi to runway holding point via J and A, do not turn left here onto TWY B.
HS2
 Potential routing error. Taxiing west on TWY A for RWY 09 departure, be aware of potential to inadvertently pass TWY G.
HS3
 Potential LVP routing error. When landing RWY 27 during LVPs, pass THR 09 and exit at TWY G, not inadvertently TWY H.

